File Original and First Copy with Department of Ecology Second Copy — Owner's Copy

WATER WELL REPORT

SC/03 - #FF Application No 15C

Third Copy - Driller's Copy STATE OF V	VASHINGTON P	ermit No	
(1) OWNER: Name Mulance Tire Station	Address 124N East Camano D	r. Camano	Is.
(2) LOCATION OF WELL: County Island	_ SE 1454U 14 Sec.	10 T 30 N. R.	O.JEWM
Bearing and distance from section or subdivision corner 120' South	n and west of fire stati	on	
(3) PROPOSED USE: Domestic Maintenal Municipal	(10) WELL LOG:		
Irrigation Test Well Other	Formation: Describe by color, character, size show thickness of aquifers and the kind and stratum penetrated, with at least one entry	e of material and stri I nature of the mater I for each change of	icture, and ial in each formation.
(4) TYPE OF WORK: Owner's number of well (if more than one)	MATERIAL	FROM	то
New well	Sand		145
Deepened ☐ Cable ■ Driven ☐ Reconditioned ☐ Rotary ☐ Jetted ☐	_ Blue clay	145	160
(I) DIMENGIONG	- 17 - 27	160	140
(5) DIMENSIONS: Diameter of well inches. Drilled 2/6 ft. Depth of completed well 2/6 ft.	11 CH	196	504.
	Sand & water	206	216
(6) CONSTRUCTION DETAILS:			
Casing installed: 6 "Diam from 0 ft. to 209 ft.			ļ
Threaded "Diam. from ft. to ft. Welded Diam. from ft. to ft. to ft.			-
			
Perforations: Yes 🗆 No 🗷			†
Type of perforator used			
perforations from ft. to ft.			
perforations from			<u> </u>
periorations from			
Screens: Yes No D John Son			
Manufacturer's Name			 -
Diam. Slot size # 16 from 41 ft. to 34 ft.			
Dlam. Slot size from ft. to ft.			
Gravel packed: Yes No L Size of gravel.			
Gravel placed fromft. toft.			_
Surface seal: Yes No D To what depth?	11.		
Material used in seal Bentonia	<u> </u>	:82	
Did any strata contain unusable water? Yes 🗌 No 💢			-
Type of water? Depth of strata	1.15.65.65.00 1.476	- : •	-
(7) PUMP: Manufacturer's Name			 -
			
(8) WATER LEVELS: Land-surface elevation above mean sea level			-
Static level 146 ft. below top of well Date 149 3. 7	"		 -
Artesian pressure			
(9) WELL TESTS: Drawdown is amount water level is lowered below static level	Work started July 27 19.81 Co	mpleted Aug 3	19.8
Was a pump test made? Yes 🗆 No 📜 If yes, by whom?	THE TRANSPORT OF THE PROPERTY		
Yield: gal./min. with ft. drawdown after hrs	This well was drilled under my it		s report
, , , , , , , , , , , , , , , , , , ,	true to the best of my knowledge a	nd belief.	
Recovery data (time taken as zero when pump turned off) (water leve	1/ 1/1/1/1/1/	20:10:	te.
measured from well top to water level/	NAME Kounds well	ation) (Type of	print)
Time Water Level Time Water Level Time Water Level	-1/27 1/ C 12-	PIC	()
	Address /9/ N. Smith	Ma yamaj	ريمون ب
	" Sunt Ka	in bill	
Date of test (119 3, 1981) Baller test 20 ga/min. with 10 ft. drawdown after. 2 hr	[Signed] (Well	Driller)	
Bailer test	··	A.K.11	2 م
Temperature of water Was a chemical analysis made? Yes [] No [License No D	Date / CO //	, 180